

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 58506

CSAH NO. 7

OVER THE

SNAKE RIVER

DISTRICT 1 - PINE COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION

BY
COLLINS ENGINEERS, INC.

JOB NO. 5221 (CEI 73)

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected at Bridge No. 58506, Piers 1 through 9, were found to be in satisfactory to fair condition. No defects of major structural significance were observed, except for a considerable amount of bracing defects and failures, which have compromised the lateral stability of the bridge. Light to moderate accumulations of timber drift were observed at Piers 2, 3, 4, 5, 7, and 8. The channel bottom around the substructure units and the shorelines appeared to be in stable condition with no significant scour or appreciable changes since the previous inspection. An adjacent retaining wall at the southeast shoreline was leaning into the channel and has failed.

INSPECTION FINDINGS:

- (A) It was observed that the retaining wall located to the east of Pier 8 was leaning into the channel and has failed.
- (B) In general, the cross-bracing between the piles of each pier was in fair to poor condition with splitting typically at one or more brace connections on each pier. Many of the pier braces also displayed moderate to heavy section loss and related connection failures.
- (C) The majority of the timber piles were in fair condition with weathering and random vertical checking present with widths of up to 1/4 inch. The only significant pile distress found was as follows:
 - * The pile at the center of Pier 2 was cracked, splintered and soft to a depth of 1/2 inch. This condition existed from 1 foot above the waterline to the channel bottom. Below this 1/2 inch softer outer layer, the wood material was sound and firm.

- * The outer 1.5 inch shell of the end pile at west end of Pier 3 was cracked and splintered. This condition was present from 6 inches below the waterline to 1.5 feet above the waterline.
 - * The outer 2 inch shell was cracked, splintered, soft, and delaminated at the second pile from the west end of Pier 4.
 - * The westernmost pile on the south side of Pier 7 was splintered over a 12 inch high by 6 inch wide by 3/4 inch deep area. This area was located 2 feet below the waterline. The material beneath the splintered material was soft to an estimated depth of 1/4 inch. The total loss of cross-section at this location was estimated to be between 10 and 20 percent.
- (D) Light accumulations of timber debris, consisting of 6 inch diameter and smaller limbs and branches, was observed at the upstream noses of Piers 2, 3, 4, and 7.
- (E) Moderate accumulation of timber debris, consisting of 1 foot diameter and smaller logs and branches, was observed around the upstream pile of Piers 5 and 8 extending from the channel bottom to the waterline.


RECOMMENDATIONS:

- (A) The cracked, split, and deteriorated pier cross-bracing should be replaced to restore the lateral stability of the piers.

- (B) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Daniel G. Stromberg

A large, stylized handwritten signature in black ink, appearing to read 'Daniel G. Stromberg', is written over a horizontal line.

Date 6/30/2008 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.

A large, stylized handwritten signature in black ink, appearing to read 'Daniel G. Stromberg', is written over a horizontal line.

Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 58506

Feature Crossed: Snake River

Feature Carried: CSAH No. 7

Location: District 1 - Pine County

Bridge Description: The superstructure consists of ten spans of timber deck on multiple timber stringers supported by nine timber pile piers and two timber pile abutments. The piers are numbered 1 through 9 starting from the north end of the bridge.

2. INSPECTION DATA

Professional Engineer/Team Leader: Daniel G. Stromberg, P.E., S.E.

Dive Team: John J. Loftus, Valerie Roustan

Date: August 23, 2007

Weather Conditions: Cloudy, 81° F

Underwater Visibility: 4.0 feet

Waterway Velocity: Negligible/None

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 through 9.

General Shape: Each pier consists of a timber cap supported by timber piles. Timber cross-bracing is present between the piles. The number of piles at each pier varies from two rows of five piles (Piers 3 and 7) to one row of seven piles (all other piers). In addition, Piers 3 and 7 have a steel nosing pile at the upstream end.

Maximum Water Depth at Substructure Inspected: Approximately 6.7 feet.

4. WATERLINE DATUM

Water Level Reference: The top of the pier cap at east end of Pier 8.

Water Surface: The waterline was approximately 9.2 feet below reference.
Water Elevation = 933.3.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 6

Item 61: Channel and Channel Protection: Code 7

Item 92B: Underwater Inspection: Code B/08/07

Item 113: Scour Critical Bridges: Code J/97

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

 Yes X No



Photograph 1. View of North Abutment, Looking Northwest.



Photograph 2. View of Pier 1, Looking Northeast.




Photograph 3. View of Pier 2, Looking Northeast.




Photograph 4. View of Pier 3, Looking Northeast.



Photograph 5. View of Pier 4, Looking Northeast.





Notes:

Refer to Figure 1 for General Notes.

Refer to Figure 1 for Inspection notes.

All soundings based on 2007 waterline location.

Legend

-7.0 Sounding Depth (8/23/07)
-7.1 Sounding Depth (9/25/02)

○ Timber Pile

○→ Battered Timber Pile

Timber Debris

**MINNESOTA
DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION**

STRUCTURE NO. 58506
OVER THE SNAKE RIVER
DISTRICT I, PINE COUNTY

INSPECTION AND SOUNDING PLAN II

Drawn By: PRH

Checked By: MDK

Code: 52210073

**COLLINS
ENGINEERS**

123 North Wacker Drive
Suite 300
Chicago, IL 60606
(312) 704-9300
www.collinsengr.com

Date: AUGUST, 2007

Scale: NTS

Figure No.: 2

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc. DATE: August 23, 2007

ON-SITE TEAM LEADER: Daniel G. Stromberg, P.E., S.E.

BRIDGE NO: 58506 WEATHER: Cloudy, 81° F

WATERWAY CROSSED: Snake River

DIVING OPERATION: X SCUBA SURFACE SUPPLIED AIR
 OTHER

PERSONNEL: John J. Loftus, Valerie Roustan

EQUIPMENT: Scuba, U/W Light, Scraper, Lead Line, Sounding Pole, Probe Rod, Camera

TIME IN WATER: 1:25 p.m.

TIME OUT OF WATER: 1:55 p.m.

WATERWAY DATA: VELOCITY Negligible/None

VISIBILITY 4.0 feet

DEPTH 6.7 feet maximum at Pier 2

ELEMENTS INSPECTED: Piers 1 through 9

REMARKS: Overall, the piles were in satisfactory to fair condition with random 1/4 inch checking and splitting. The timber bracing at all piers was in fair to poor condition with splitting, section loss, and damage at the connections. The retaining wall adjacent to Pier 8 was leaning and has failed. Light to moderate accumulations of timber drift were observed around the upstream pile of Piers 2, 3, 4, 5, 7, and 8. The channel bottom consisted of 6 to 12 inch diameter riprap with random deposits consisting of silty sand and organic material. The channel bottom appeared to be stable with no evidence of significant scour.

FURTHER ACTION NEEDED: X YES NO

Replace the cracked, split, and deteriorated pier cross-bracing to restore lateral stability of the piers.

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 58506
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Daniel G. Stromberg, P.E., S.E.
WATERWAY CROSSED Snake River

INSPECTION DATE August 23, 2007
NOTE: USE ALL APPLICABLE CONDITION
DEFINITIONS AS DEFINED IN THE MINNESOTA
RECORDING AND CODING GUIDE INCLUDING
GENERAL, SUBSTRUCTURE, CHANNEL AND
PROTECTION, AND CULVERTS AND WALL
DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER (BRACING)	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Pier 1	5.7'	6	N	N	8	5	6	8	7	7	N	7	N	N	6	N	N	N
	Pier 2	6.7'	6	N	N	8	5	6	8	N	N	7	7	N	N	6	N	N	N
	Pier 3	5.1'	6	N	N	8	5	6	8	N	N	7	7	N	N	6	N	N	N
	Pier 4	4.9'	6	N	N	8	5	6	8	N	N	7	7	N	N	6	N	N	N
	Pier 5	4.1'	6	N	N	8	5	6	8	N	N	7	7	N	N	6	N	N	N
	Pier 6	5.3	6	N	N	8	5	6	8	N	N	N	8	N	N	6	N	N	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the piles were in satisfactory to fair condition with random 1/4 inch checking and splitting. The timber bracing at all piers was in fair to poor condition with splitting, section loss, and damage at the connections. The retaining wall adjacent to Pier 8 was leaning and has failed. Light to moderate accumulations of timber drift were observed around the upstream pile of Piers 2, 3, 4, 5, 7, and 8. The channel bottom consisted of 6 to 12 inch diameter riprap with random deposits consisting of silty sand and organic material. The channel bottom appeared to be stable with no evidence of significant scour.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO.
USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 58506
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Daniel G. Stromberg, P.E., S.E.
WATERWAY CROSSED Snake River

INSPECTION DATE August 23, 2007
NOTE: USE ALL APPLICABLE CONDITION
DEFINITIONS AS DEFINED IN THE MINNESOTA
RECORDING AND CODING GUIDE INCLUDING
GENERAL, SUBSTRUCTURE, CHANNEL AND
PROTECTION, AND CULVERTS AND WALL
DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

			SUBSTRUCTURE						CHANNEL					GENERAL					
UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER (BRACING)	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Pier 7	5.0'	6	N	N	8	5	6	8	N	N	7	7	N	N	6	N	N	N
	Pier 8	3.6'	6	N	N	8	5	6	8	N	N	7	7	N	N	6	N	N	N
	Pier 9	0.5'	6	N	N	8	5	6	8	7	N	N	7	N	N	6	N	N	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the piles were in satisfactory to fair condition with random 1/4 inch checking and splitting. The timber bracing at all piers was in fair to poor condition with splitting, section loss, and damage at the connections. The retaining wall adjacent to Pier 8 was leaning and has failed. Light to moderate accumulations of timber drift were observed around the upstream pile of Piers 2, 3, 4, 5, 7, and 8. The channel bottom consisted of 6 to 12 inch diameter riprap with random deposits consisting of silty sand and organic material. The channel bottom appeared to be stable with no evidence of significant scour.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO.
USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.